

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: juan-dre@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-07-26 08:44:08  
Technician Name: Wimpie F  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Make: VW  
VIN: WVVZZZAAZKD176682  
Odometer: 89240 km  
Vehicle Software Version: V10.23

## Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.09 Electronic Central Electric
- 4.10 Parallel Parking 2
- 5.15 Airbag
- 6.17 Instrument Cluster
- 7.19 Data Bus OBD Interface
- 8.25 Anti-Theft Immobilizer
- 9.44 Power Steering
- 10.5F Information Electronics 1