

| Year | 2019 |
|---------------|-------------------|
| Km | 69162 |
| Transmission | Automatic |
| Colour | SILVER |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|----------------------|---|------------------|----------------------|----------|
| Radio / Entertainment | Within Specification | - | Aircon Controls | Within Specification | - |
| Cluster | Within Specification | • | Electric Windows | Within Specification | • |

| Exterior | | | | | |
|-------------------------|----------------------|------------|--------------|----------------------|---|
| Windscreen | Within Specification | | Mag Wheels | Within Specification | - |
| Side Mirrors / Electric | Within Specification | lacksquare | Wiper Blades | Within Specification | • |

| BOSCH VEHICLE INSPECTION | | | | | |
|--------------------------|----------------------|--|---------------------|----------------------|----------|
| Engine | Engine | | | | |
| Oil Service | SERVICE DUE Km | | Dip Stick | Within Specification | ~ |
| Oil Filter | Renewed | | Oil Filler Cap | Within Specification | ~ |
| Fuel/Diesel Filter | Within Specification | | Fan Belt | No Cracks | ~ |
| Air Filter | Within Specification | | Fan belt Tensioner | Within Specification | • |
| Cabin Filter | Within Specification | | Alternator Belt | No Cracks | ~ |
| Spark Plugs | Within Specification | | Power Steering Belt | No Cracks | ~ |
| Brake Fluid | Within Specification | | Aircon Belt | No Cracks | ~ |
| Antifreeze | Within Specification | | Multi V belt | No Cracks | ~ |
| Rear Main Seal | No Visible Leaks | | Engine Mountings | Within Specification | ~ |
| Sump/Gasket | No Visible Leaks ▼ | | PCV Valve | Within Specification | ~ |

| Braking System | | |
|--------------------|----------------------|------------|
| Front Brake Pads | 80% | • |
| Front Brake Discs | Within Specification | • |
| Front Brake Sensor | Within Specification | • |
| Rear Brake Pads | 80% | • |
| Rear Brake Discs | Within Specification | • |
| Rear Brake Sensor | Within Specification | • |
| Rear Drums | Within Specification | • |
| Rear Linings | 80% | • |
| Brake Master | Within Specification | lacksquare |
| Hand Brake | Within Specification | • |
| Brake Calipers | Within Specification | • |
| Brake Hose | Within Specification | • |

| Cooling System | | |
|-------------------|----------------------|----------|
| Radiator | No Visible Leaks | • |
| Radiator Hoses | No Visible Leaks | • |
| Waterpump | No Visible Leaks | • |
| Thermostat | Within Specification | • |
| Aircon Gas | Within Specification | \ |
| Aircon Pump | Within Specification | • |
| Aircon Condensor | Within Specification | • |
| Interior Fan | Within Specification | • |
| Interior Radiator | No Visible Leaks | • |

| Fueling System | | |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | - |
| Throttle | Within Specification | • |
| Turbo | Within Specification | • |
| Injectors | Within Specification | - |
| Fuel Pump | Within Specification | • |
| Fuel Lines | Within Specification | • |

| Ignition System | | |
|-----------------|----------------------|----------|
| Ignition Coils | Within Specification | — |
| Glow Plugs | Not Applicable | • |
| Distrubutor | Not Applicable | — |
| HT Leads | Not Applicable | • |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------------|------------|
| Steering Rack | Within Specification | lacksquare |
| Power Steering Pump | Within Specification | • |
| Wheel Alignment | Within Specification | lacksquare |
| CV Joints | Within Specification | • |
| CV Boots | Within Specification | • |
| Shocks Front | Within Specification | • |
| Shock Mountings Front | Within Specification | • |
| Shocks Rear | Within Specification | lacksquare |
| Stabilizer Links | Within Specification | • |
| Wheel Bearings | Within Specification | • |
| Bearing Hubs | Within Specification | • |
| Control Arms | Within Specification | • |
| Sideshafts/Seal | Within Specification | • |
| Propshaft | Not Applicable | • |
| Wheel Nuts/Studs | Within Specification | • |
| Tyres & Spare | Within Specification | |
| Mag Wheels/Hub Caps | Within Specification | — |

| Transmission & Clutch | | |
|-----------------------|----------------------|---|
| Clutch Kit | Not Applicable | |
| Clutch Master | Not Applicable | |
| Clutch Slave | Not Applicable | |
| Clutch Cable | Within Specification | |
| Gearbox | Not Applicable | |
| Gear & Diff oil | Within Specification | |
| Auto Transmission | Within Specification | |
| Gear Selector | Within Specification | |
| Gear Linkages | Within Specification | • |

| Ignition System | | |
|------------------|----------------------|---|
| Diagnostics | No Fault Code | - |
| Cyl Leakage Test | Within Specification | - |
| Road Test | Within Specification | - |
| Handling | Within Specification | • |

| Concluding Remarks | |
|--------------------|--------------------|
| | |
| | |
| | |
| | |
| Bosch Technician | General Comments |
| Elias Makubela | |
| | |
| NEW Technician | Date of Inspection |
| | |
| | |



