

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 11/13/2024 16:32:50

Technician Name: Elias

## Vehicle Information

Year: 2018

Make: USAFORD

Model: Fiesta

VIN: WF0JXXGAHJU17763

Displacement: G 1.0 T-GDI KAPPA

Odometer: 69166 km

Vehicle Software Version: V10.76

## Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCMII (Body Control Module)
5. DDM (Driver Front Door Module)
6. GWM (Gateway Module A)
7. HVAC (Heating Ventilation Air Conditioning)
8. IPC (Instrument Panel Control Module)
9. PAM (Parking Aid Module)
10. PCM (Powertrain Control Module)
11. PDM (Passenger Front Door Module)
12. PSCM (Power Steering Control Module)
13. RCM (Restraint Control Module)
14. SCCM (Steering Column Control Module)