

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15390

Make	FORD
Model	FIESTA 1.4 AMBIENTE 5 Dr
Vin	WF0DXXGAKDHJ17850
Engine Specifications	1.4 Petrol
Vehicle Type	C/P
Service Plan	N/A

Year	2017
Km	124667
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	-	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	-
Oil Filter	Good Condition	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	Fan Belt	Not Applicable	•
Air Filter	Within Specification	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Within Specification	Alternator Belt	Good Condition	•
Spark Plugs	No Fault Code	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	Multi V belt	Good Condition	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	PCV Valve	No Visible Leaks	•

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	40%	•
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	-
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Good Condition	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	-
Glow Plugs	Not Applicable	-
Distrubutor	Not Applicable	-
HT Leads	No Visible Leaks	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	-
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	-
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	-
Stabilizer Links	Within Specification	-
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	-
Sideshafts/Seal	No Visible Leaks	-
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	-
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	•
Handling	Within Specification	-

Concluding Remarks

Bosch Technician

Dries Olwagen

NEW Technician

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

