

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-08-20 07:45:58

Technician Name: Dries

Order no:

Service fee:

Notes:

Vehicle Information

Make: FIAT

VIN: ZFA3120000J418203

Displacement: G 1.2 MPI

Odometer: 91335 km

Vehicle Software Version: V10.72

Inspection Result

The following systems are OK:

1. BCM (Body Control Module)
2. EPS (Electric Power Steering)
3. ECM (Engine Control Module)
4. ABS (Anti-Lock Braking System)
5. CTM (Convergence Telematic Module)
6. PAM (Parking Aid Module)
7. IPC (Instrument Panel Cluster)
8. HVAC (Heating Ventilation Air-Conditioning And Cooling)
9. ORC (Occupant Restraint)