Make	SUZUKI	
Model	GRAND VITARA 2.4	
Vin	JSAJTDA4V00219101	
Engine Specifications	2.4	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2011
Km	195993
Transmission	Manual
Colour	GOLD
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Within Specification		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	—
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	—
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	—
Brake Calipers	Within Specification	—
Brake Hose	Within Specification	—

Cooling System		
Radiator	No Visible Leaks	_
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	_
Thermostat	Within Specification	_
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	\rightarrow
Fuel Pump	Within Specification	~
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	—
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	-
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	~
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	~
Gearbox	Within Specification	~
Gear & Diff oil	Within Specification	~
Auto Transmission	Not Applicable	—
Gear Selector	Within Specification	~
Gear Linkages	Within Specification	~

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Elias Makubela	
NEW Technician	Date of Inspection



