

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/01/2024 12:37:35

Technician Name:Christiaan

Vehicle Information

Make:SUZUKI

VIN:JSAJTDA4V00219101

Displacement:D 1.4 TCI-U2

Odometer:196020 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-Lock Braking System)
- 3.SRS (Supplemental Inflatable Restraint System/Airbag)
- 4.AC (Air Conditioning)
- 5.BCM (Body Control Module)
- 6.4WD (4 Wheel Drive)