

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 18325

Make	SUZUKI	
Model	SWIFT 1.2 GL	
Vin	MA3GZC62S00A195	72
Engine Specifications	1.2	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2016
Km	97287
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	•
Cluster	Within Specification	-	Electric Windows	Within Specification	-

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification
Oil Filter	Within Specification	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	Fan Belt	No Cracks
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	No Cracks
Spark Plugs	Within Specification	Power Steering Belt	No Cracks
Brake Fluid	No Visible Leaks	Aircon Belt	No Cracks
Antifreeze	No Visible Leaks	Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	-
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	-
Aircon Gas	No Visible Leaks	-
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

