

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/11/2024 11:52:15

Technician Name:Dries

Vehicle Information

Make:NISSAN

VIN:adnusun1d5u0199160

Displacement:G 1.4 DOHC

Odometer:128900 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.Anti-lock Brake System(ABS)
- 2.Body Control System(BCM)
- 3.Supplemental Restraint System(SRS)