

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:11/04/2024 16:35:13

Technician Name:Eugene

Vehicle Information

Year:2017

Make:HYUNDAI

Model:Creta(GS)

VIN:MALC381UMHM203096

Displacement:D 1.6 TCI-U2

Odometer:70559 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.Body Control Module
- 7.Cluster Module
- 8.Smart Junction Block
- 9.EPS (Electronic Power Steering)
- 10.IMM (Immobilizer)
- 11.CODE (Transmitter Code Saving)