

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-06-21 09:07:26
Technician Name: Mike Jones
Order no:
Service fee:
Notes:

Vehicle Information

Make: NISSAN
VIN: JN1BDAV37U0203716
Displacement: G 1.2 MPI
Odometer: 149097 km
Vehicle Software Version: V10.32

Inspection Result

HVAC 2 problems exist

1. B2631-00 Sunload Sensor

CRNT

2. B277F-00 Heat Sensor (Driver Side)

CRNT

The following systems are OK:

1. ENGINE
2. ABS
3. METER/M&A
4. BCM
5. AIR BAG
6. ICC/ADAS
7. TRANSMISSION
8. MULTI AV
9. EPS/DAST 3
10. IPDM E/R
11. AIR PRESSURE MONITOR
12. HEAD LAMP LEVELIZER
13. SONAR
14. CAN GATEWAY
15. POP UP HOOD
16. ANC
17. EMCM
18. CHASSIS CONTROL
19. FSCM