

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14635

Make	MERCEDES-BENZ
Model	C180 AMG LINE A/T
Vin	WF0AXXWPMAEJ39662
Engine Specifications	Petrol
Vehicle Type	S/D
Service Plan	N/A

Year	2018
Km	95919
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	-

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Within Specification	•

### **BOSCH VEHICLE INSPECTION**

Engine					
Oil Service		7 Km	Dip Stick	Good Condition	
Oil Filter	Not Applicable	•	Oil Filler Cap	No Visible Leaks	
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable	
Air Filter	Within Specification	•	Fan belt Tensioner	Not Applicable	
Cabin Filter	Within Specification	•	Alternator Belt	Not Applicable	
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	
Brake Fluid	No Visible Leaks	•	Aircon Belt	Not Applicable	
Antifreeze	No Visible Leaks	•	Multi V belt	Not Applicable	
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Renewed	•
Rear Brake Pads	100%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Renewed	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Within Specification	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

#### Bosch Technician

Raymond Mncube

**NEW Technician** 

## General Comments

Date of Inspection

16-Jul-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

