| Make | FORD | | |
|-----------------------|---------------------------------------|--------|--|
| Model | RANGER 2.0D BI-TURBO WILDTRAK A/T P/U | | |
| Vin | AFAPXXMJ2PKY22665 | | |
| Engine Specifications | 2.0 | Diesel | |
| Vehicle Type | D/C | | |
| Service Plan | N/A | | |

| Year | 2019 |
|---------------|-------------------|
| Km | 93898 |
| Transmission | Automatic |
| Colour | GREY |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|-------------------|---|------------------|-------------------|---|
| Radio / Entertainment | Working Condition | - | Aircon Controls | Working Condition | • |
| Cluster | Good Condition | • | Electric Windows | Working Condition | • |

| Exterior | | | | | |
|-------------------------|----------------------|---|--------------|----------------------|--------------------|
| Windscreen | Within Specification | • | Mag Wheels | Good Condition | • |
| Side Mirrors / Electric | Within Specification | • | Wiper Blades | Within Specification | \rightarrow |

| BOSCH VEHICLE INSPECTION | | | | | |
|--------------------------|----------------------|----------|---------------------|----------------------|----------|
| Engine | | | | | |
| Oil Service | | 90989 Km | Dip Stick | Good Condition | V |
| Oil Filter | No Visible Leaks | - | Oil Filler Cap | Within Specification | • |
| Fuel/Diesel Filter | No Visible Leaks | — | Fan Belt | No Cracks | • |
| Air Filter | Within Specification | - | Fan belt Tensioner | Within Specification | • |
| Cabin Filter | Within Specification | - | Alternator Belt | No Cracks | • |
| Spark Plugs | Not Applicable | - | Power Steering Belt | Not Applicable | - |
| Brake Fluid | No Visible Leaks | - | Aircon Belt | No Cracks | - |
| Antifreeze | No Visible Leaks | - | Multi V belt | No Cracks | ~ |
| Rear Main Seal | No Visible Leaks | • | Engine Mountings | Within Specification | • |
| Sump/Gasket | No Visible Leaks | • | PCV Valve | Within Specification | • |

| Braking System | | |
|--------------------|----------------------|------------|
| Front Brake Pads | 60% | • |
| Front Brake Discs | Within Specification | • |
| Front Brake Sensor | Not Applicable | • |
| Rear Brake Pads | -Select- | lacksquare |
| Rear Brake Discs | Not Applicable | |
| Rear Brake Sensor | Not Applicable | lacksquare |
| Rear Drums | Within Specification | lacksquare |
| Rear Linings | 60% | • |
| Brake Master | No Visible Leaks | • |
| Hand Brake | Within Specification | |
| Brake Calipers | No Visible Leaks | • |
| Brake Hose | No Visible Leaks | • |

| Cooling System | | |
|-------------------|----------------------|---|
| Radiator | No Visible Leaks | • |
| Radiator Hoses | No Visible Leaks | • |
| Waterpump | Within Specification | • |
| Thermostat | Within Specification | • |
| Aircon Gas | No Visible Leaks | • |
| Aircon Pump | Within Specification | • |
| Aircon Condensor | No Visible Leaks | • |
| Interior Fan | Within Specification | • |
| Interior Radiator | No Visible Leaks | _ |

| Fueling System | | |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | - |
| Throttle | Within Specification | • |
| Turbo | Within Specification | • |
| Injectors | Within Specification | • |
| Fuel Pump | Within Specification | • |
| Fuel Lines | No Visible Leaks | • |

| Ignition System | | |
|-----------------|----------------|------------|
| Ignition Coils | Not Applicable | • |
| Glow Plugs | No Fault Code | • |
| Distrubutor | Not Applicable | • |
| HT Leads | Not Applicable | lacksquare |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------------|------------|
| Steering Rack | Within Specification | - |
| Power Steering Pump | Not Applicable | • |
| Wheel Alignment | Within Specification | |
| CV Joints | Not Applicable | lacksquare |
| CV Boots | Not Applicable | • |
| Shocks Front | Within Specification | |
| Shock Mountings Front | Within Specification | • |
| Shocks Rear | No Visible Leaks | • |
| Stabilizer Links | Within Specification | • |
| Wheel Bearings | Within Specification | |
| Bearing Hubs | Within Specification | • |
| Control Arms | Within Specification | • |
| Sideshafts/Seal | No Visible Leaks | • |
| Propshaft | Within Specification | • |
| Wheel Nuts/Studs | Within Specification | • |
| Tyres & Spare | Within Specification | • |
| Mag Wheels/Hub Caps | Within Specification | • |

| Transmission & Clutch | | |
|-----------------------|----------------------|----------|
| Clutch Kit | Not Applicable | - |
| Clutch Master | Not Applicable | - |
| Clutch Slave | Not Applicable | — |
| Clutch Cable | Not Applicable | - |
| Gearbox | Within Specification | — |
| Gear & Diff oil | No Visible Leaks | - |
| Auto Transmission | Within Specification | — |
| Gear Selector | Good Condition | — |
| Gear Linkages | Within Specification | — |

| Ignition System | | |
|------------------|----------------------|---|
| Diagnostics | No Fault Code | • |
| Cyl Leakage Test | No Visible Leaks | - |
| Road Test | Within Specification | - |
| Handling | Within Specification | • |

| Concluding Remarks | |
|--------------------|--------------------|
| | |
| | |
| | |
| | |
| Bosch Technician | General Comments |
| Raymond Mncube | |
| | |
| NEW Technician | Date of Inspection |
| | 23-Dec-2024 |



PRETORIA

