

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-22 12:23:34
Technician Name: Wimpie F
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2020
Make: KIA
Model: Carnival/Sedona(YP)
VIN: KNAMB81AML6623291
Displacement: D 2.2 TCI R
Odometer: 97980 km
Vehicle Software Version: V10.50

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. TCM (Transmission Control Module)
3. ESP (Electronic Stability Program)
4. Airbag (Event #1)
5. Airbag (Event #2)
6. AC (Air Conditioning)
7. IC (Instrument Cluster)
8. SJB (Smart Junction Block)
9. DDM (Driver Door Module)
10. IBU-TPMS
11. IBU-BCM
12. RVM (Rear View Monitor)
13. IMMO (Immobilizer)
14. CODE (Transmitter Code Saving)