

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 17143

Make	AUDI	
Model	Q2 2.0 TDI SPORT STRONIC	
Vin	WAUZZZGA6JA024344	
Engine Specifications	2.0 Diesel	•
Vehicle Type	SUV	
Service Plan	N/A	

Year	2018
Km	114255
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION

Oil ServiceKmDip StickGood ConditionImage: C						
Fuel/Diesel FilterWithin SpecificationImage: ConditionFan BeltWithin SpecificationImage: ConditionAir FilterGood ConditionImage: ConditionIm	Oil Service		Km	Dip Stick	Good Condition	-
Air FilterGood ConditionImage: ConditionFan belt TensionerWithin SpecificationCabin FilterNot ApplicableImage: ConditionAlternator BeltWithin SpecificationImage: ConditionSpark PlugsNot ApplicableImage: ConditionImage: ConditionAlternator BeltWithin SpecificationImage: ConditionBrake FluidGood ConditionImage: ConditionImage: ConditionImage: ConditionImage: ConditionImage: ConditionImage: ConditionAntifreezeGood ConditionImage: Condition </td <td>Oil Filter</td> <td>Within Specification</td> <td>-</td> <td>Oil Filler Cap</td> <td>Good Condition</td> <td>•</td>	Oil Filter	Within Specification	-	Oil Filler Cap	Good Condition	•
Cabin FilterNot ApplicableImage: Constraint of the sector of the s	Fuel/Diesel Filter	Within Specification	-	Fan Belt	Within Specification	-
Spark Plugs Not Applicable Image: Power Steering Belt Within Specification Image: Power Steering Belt Brake Fluid Good Condition Image: Power Steering Belt Within Specification Image: Power Steering Belt Antifreeze Good Condition Image: Power Steering Belt Within Specification Image: Power Steering Belt Rear Main Seal Within Specification Image: Power Steering Belt Within Specification Image: Power Steering Belt	Air Filter	Good Condition	-	Fan belt Tensioner	Within Specification	-
Brake Fluid Good Condition Image: Condition Aircon Belt Within Specification Antifreeze Good Condition Image: Condition Image: Condition Rear Main Seal Within Specification Image: Condition	Cabin Filter	Not Applicable	-	Alternator Belt	Within Specification	-
Antifreeze Good Condition Image: Multi V belt Within Specification Rear Main Seal Within Specification Image: Multi V belt	Spark Plugs	Not Applicable	-	Power Steering Belt	Within Specification	•
Rear Main Seal Within Specification Image: Construction Engine Mountings Within Specification	Brake Fluid	Good Condition	-	Aircon Belt	Within Specification	•
	Antifreeze	Good Condition	-	Multi V belt	Within Specification	•
Sump/Gasket Within Specification PCV Valve Within Specification	Rear Main Seal	Within Specification	-	Engine Mountings	Within Specification	•
	Sump/Gasket	Within Specification	-	PCV Valve	Within Specification	-



Braking System		
Front Brake Pads	20%	•
Front Brake Discs	Not Applicable	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	20%	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Not Applicable	•
Hand Brake	Not Applicable	•
Brake Calipers	Not Applicable	•
Brake Hose	Not Applicable	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Not Applicable	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	-

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	-
Turbo	Good Condition	-
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	No Visible Leaks	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	•
Cyl Leakage Test	Good Condition	-
Road Test	Not Applicable	•
Handling	Not Applicable	-

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

