

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14965

Make	SUZUKI			
Model	JIMNY 1.5 GLX			
Vin	MA3NFG81S00	146406		
Engine Specifications	1.5	Petrol	-	
Vehicle Type				
Service Plan	N/A			,

Year	2022
Km	21966
Transmission	Manual
Colour	GREEN
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	-	Fan Belt	Not Applicable	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	-	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	-	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	-	Multi V belt	No Cracks	•
Rear Main Seal	Within Specification	-	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	-	PCV Valve	Within Specification	•

# BOSCH INSPECTION REPORT

Braking	System
	- )

Front Brake Pads	80%	-
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	-
Rear Linings	80%	-
Brake Master	Within Specification	-
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	-
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	-
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	-
Injectors	Within Specification	-
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Within Specification	-



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Within Specification	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

Eugene J.v. Rensburg

**NEW Technician** 

## General Comments

Date of Inspection

29-Jul-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

