

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:10/28/2024 10:49:53
Technician Name:Juan-Dre

Vehicle Information

Year:2018
Make:MAZDA
Model:MAZDA3 / AXELA
VIN:JM6BN24Z5J0245214
Displacement:G 1.4 MPI KAPPA
Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.F_BCM (Front Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.R_BCM (Rear Body Control Module)
- 5.RCM (Restraint Control Module)
- 6.ABS (Anti-Lock Brake System)
- 7.CMU (Connectivity Master Unit)
- 8.EPS (Electronic Power Steering)
- 9.SSU#1 (Start Stop Unit)