

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14632

Make	VOLKSWAGEN	
Model	JETTA VI 1.6 TDi COMFORTI	INE
Vin	WVWZZZ16ZDM024749	
Engine Specifications	1.6 Petro	•
Vehicle Type	S/D	
Service Plan	N/A	

Year	2013
Km	119749
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Within Specification	-

### **BOSCH VEHICLE INSPECTION**

8				
Oil Service		113278 Km	Dip Stick	No Visible Leaks
Oil Filter	No Visible Leaks	•	Oil Filler Cap	No Visible Leaks
Fuel/Diesel Filter	No Visible Leaks	•	Fan Belt	Within Specification
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification
Spark Plugs	Not Applicable	•	Power Steering Belt	Not Applicable
Brake Fluid	No Visible Leaks	•	Aircon Belt	Within Specification
Antifreeze	No Visible Leaks	•	Multi V belt	Within Specification
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification



Within Specification

No Visible Leaks

Not Applicable

No Visible Leaks

Within Specification

No Visible Leaks

No Visible Leaks

-Select-

•

•

◄

•

•

•

•

-

•

•

•

◄

Braking System	
Front Brake Pads	-Select-
Front Brake Discs	Within Specification
Front Brake Sensor	Renewed
Rear Brake Pads	-Select-

**Rear Brake Discs** 

Rear Brake Sensor

Rear Drums

**Rear Linings** 

Brake Master

Hand Brake

Brake Hose

**Brake Calipers** 

A

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	-
Injectors	Not Applicable	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	-
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

Raymond Mncube

**NEW Technician** 

## General Comments

Date of Inspection

15-Jul-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

