

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:@boschgezina.co.za

Sn:988579800333

Time:10/30/2024 08:12:57

Technician Name:Christiaan

## Vehicle Information

Year:2008

Make:ROMEO

Model:MITO

VIN:ZAR9550000X025930

Odometer:69819 km

Vehicle Software Version:V10.78

## Inspection Result

The following systems are OK:

- 1.BCM (Body Control Module)
- 2.EPS (Electric Power Steering)
- 3.TCM (Transmission Control Module)
- 4.ABS (Anti-Lock Braking System)
- 5.ECM (Engine Control Module)
- 6.ORB (Occupant Restraint)
- 7.PAM (Parking Aid Module)
- 8.ETM (Entertainment Telematic Module)
- 9.HVAC (Heating Ventilation Air-Conditioning And Cooling)
- 10.IPC (Instrument Panel Cluster)