Make	VOLKSWAGEN		
Model	CADDY KOMBI 1.6i (7 SEAT)		
Vin	WV2ZZZSK5PX026306	6	
Engine Specifications	1.6	Petrol	
Vehicle Type	MPV		
Service Plan	N/A		

Year	2023
Km	60463
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	_
Cluster	Within Specification	-	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	—	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Within Specification		Multi V belt	No Cracks	_
Rear Main Seal	Within Specification		Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	-
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	lacksquare

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	\rightarrow
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	Within Specification	lacksquare
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	
Sideshafts/Seal	Within Specification	
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	lacksquare

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	
Clutch Slave	Within Specification	
Clutch Cable	Within Specification	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	Within Specification	
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Elias Makubela	
Lilas ivianubeia	
NEW Technician	Date of Inspection



