

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 10/31/2024 09:11:27
Technician Name: Elias

Vehicle Information

Year: 2023
Make: VW_CV
VIN: WV2ZZZSK5PX026306
Odometer: 060470 km
Vehicle Software Version: V10.28

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.17 Instrument Cluster
- 7.19 Data Bus OBD Interface
- 8.23 Brake Boost
- 9.42 Driver's Door Electronics
- 10.44 Power Steering
- 11.52 Passenger's Door Electronics
- 12.5F Information Electronics 1
- 13.69 Trailer Function
- 14.76 Parking Aid