

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-10-11 11:47:48

Technician Name:Riaan

Customer Name:citton

Order no:

Service fee:

Notes:

Vehicle Information

Year:2019

Make:HYUNDAI

Model:Grand i10/Xcent(BA)

VIN:MALA851CLKM926471

Displacement:G 1.2 MPI

Odometer:72823 km

Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.BCM (Body Control Module)
- 6.IC (Cluster Module)
- 7.MDPS (Motor Driven Power Steering)
- 8.IMMO (Immobilizer)
- 9.CODE (Transmitter Code Saving)