Make	ТОУОТА	
Model	STARLET 1.4 Xi	
Vin	JTDGWC52S0082760	11
Engine Specifications	1.4	Petrol
Vehicle Type	H/B	

Year	2022
Km	32955
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	<b>~</b>
Cluster	Within Specification	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Not Applicable	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		30221 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition	•	Aircon Belt	No Cracks	<b>~</b>
Antifreeze	Good Condition	<b>—</b>	Multi V belt	No Cracks	<b>~</b>
Rear Main Seal	No Visible Leaks	<b>~</b>	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	V	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	<b>\rightarrow</b>
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	<b>~</b>
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	<b>—</b>
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>—</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>~</b>
Power Steering Pump	Not Applicable	_
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	_
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	-
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	_
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	-
Tyres & Spare	Good Condition	_
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Within Specification	<b>—</b>
Clutch Master	Within Specification	<b>—</b>
Clutch Slave	Within Specification	<b>T</b>
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	<b>~</b>

Ignition System		
Diagnostics	No Fault Code	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	_
Handling	Good Condition	<b>~</b>

Concluding Remarks		

Bosch Technician	
-Select-	•

General Comments		

NEW Technician	
RIAAN MEINTJIES	

Date of Inspection	
17-Jul-2024	



