

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:11/01/2024 10:40:02
Technician Name:Christiaan

Vehicle Information

Year:2019
Make:NISSAN
Model:Almera
VIN:MDHBBAN17Z0728674
Displacement:D 1.4 TCI-U2
Odometer:56644 miles
Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.Engine Control Module(ECM)
- 2.Anti-lock Brake System(ABS)
- 3.Instrument cluster(IC)
- 4.Body Control System(BCM)
- 5.Supplemental Restraint System(SRS)
- 6.Transmission Control Module(TCM)
- 7.Electric Power Steering(EPS)
- 8.Intelligent Power Distribution Unit(IPDU)

