

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 15300

Make	CHEVROLET		
Model	TRAILBLAZER 2.8 LTZ 4X4 A/T		
Vin	MMM156MK0GH6294	463	
Engine Specifications	2.8	Diesel	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2016
Km	147012
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Not Applicable	-	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Not Applicable	-

## **BOSCH VEHICLE INSPECTION**

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	•
Oil Filter	Not Applicable	Oil Filler Cap	No Visible Leaks	-
Fuel/Diesel Filter	Within Specification	Fan Belt	No Cracks	•
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	No Cracks	-
Spark Plugs	Not Applicable	Power Steering Belt	No Cracks	•
Brake Fluid	Good Condition	Aircon Belt	No Cracks	•
Antifreeze	Good Condition	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	-
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Within Specification	-
Brake Calipers	Good Condition	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	-
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Not Applicable	•
Aircon Pump	Within Specification	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	Not Applicable	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

**RIAAN MEINTJIES** 

-Select-

## General Comments

Date of Inspection

14-Aug-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

