

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-08-14 15:55:32

Technician Name:Riaan

Customer Name:citton cars

Order no:

Service fee:

Notes:

Vehicle Information

Year:2016

Make:CHEVROLET

Model:Trailblazer

VIN:MMM156MK0GH629463

Displacement:G 1.6 GDI GAMMA

Odometer:147015 km

Vehicle Software Version:V10.54

Inspection Result

The following systems are OK:

- 1.Engine Control Module (ECM)
- 2.Transmission Control Module (TCM)
- 3.Transfer Case Control Module (TCCM)
- 4.Electronic Brake Control Module (EBCM)
- 5.Multi-Axis Acceleration Sensor Module (MAASM)
- 6.Steering Wheel Angle Sensor Module (SWASM)
- 7.Body Control Module (BCM)
- 8.Inflatable Restraint Sensing And Diagnostic Module (IRSDM)
- 9.Instrument Cluster (IC)
- 10.Radio (RADIO)
- 11.Heating Ventilation And Air Conditioning Control Module (HVACCM)
- 12.Parking Assist Control Module (PACM)