

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:02/04/2025 11:13:09

Technician Name:John

Vehicle Information

Year:2018

Make:VW

VIN:AAVZZZAWZJU029771

Displacement:G 1.2 MPI KAPPA

Odometer:76431 km

Vehicle Software Version:V10.28

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.3C Lane Change Assistance
- 10.44 Power Steering
- 11.5F Information Electronics 1
- 12.76 Parking Aid
- 13.CA Sunroof Control Module
- 14.8118 Airbag 2