

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Sn:988579800333

Time:2024-10-03 08:14:08

Technician Name:Ricardo

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2017

Make:TOYOTA

Model:Hilux

VIN:AHTKB8CD702978888

Displacement:G 1.2 DOHC

Odometer:78593.00 km

Vehicle Software Version:V10.48

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.RCC (Radar Cruise) 1
- 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.FWD (Four Wheel Drive)
- 7.CM (Combination Meter)
- 8.NS (Navigation System)