Make	NISSAN		
Model	ALMERA 1.5 ACENTA A/T		
Vin	MDHBBAN17Z072	9813	
Engine Specifications	1.5	Petrol	-
Vehicle Type	H/B		
Service Plan	N/A		

Year	2019
Km	29813
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Working Condition	-	Electric Windows	Working Condition	V

Exterior					
Windscreen	Good Condition		Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	No Visible Leaks	—
Oil Filter	No Visible Leaks	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable	•
Air Filter	Good Condition	•	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Good Condition	•	Alternator Belt	Not Applicable	•
Spark Plugs	Good Condition	•	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	•	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	•	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Good Condition	—
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	20%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Good Condition	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	~
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Visible Leaks	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Good Condition	lacksquare
Interior Radiator	No Visible Leaks	—

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	No Visible Leaks	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Good Condition	•
HT Leads	Good Condition	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	
Control Arms	Within Specification	
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	lacksquare
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	—
Clutch Master	Not Applicable	—
Clutch Slave	Not Applicable	\
Clutch Cable	Not Applicable	V
Gearbox	Good Condition	T
Gear & Diff oil	No Visible Leaks	—
Auto Transmission	No Visible Leaks	—
Gear Selector	Good Condition	—
Gear Linkages	Good Condition	T

Ignition System		
Diagnostics	Good Condition	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	~
Handling	Good Condition	•

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
JOHN TSIPA	28-Oct-2024



