

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:10/28/2024 13:02:23

Technician Name:john

## Vehicle Information

Make:NISSAN

Odometer:121683 km

Vehicle Software Version:V10.48

## Inspection Result

The following systems are OK:

- 1.Engine Control Module(ECM)
- 2.Anti-lock Brake System(ABS)
- 3.Instrument cluster(IC)
- 4.Body Control System(BCM)
- 5.Supplemental Restraint System(SRS)
- 6.Transmission Control Module(TCM)
- 7.Electric Power Steering(EPS)
- 8.Intelligent Power Distribution Unit(IPDU)