

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:jaun-dre@boschgezina.co.za  
Sn:988579800333  
Time:2024-07-26 14:06:38  
Technician Name:bote  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2014  
Make:USAFORD  
Model:Ranger / Mazda B-Ser  
VIN:AFAPXXMJ2PER30135  
Displacement:G 1.0 MPI KAPPA  
Odometer:125380 miles  
Vehicle Software Version:V10.76

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.BCMII (Body Control Module)
- 4.FCDIM (Front Control/Display Interface Module)
- 5.HVAC (Heating Ventilation Air Conditioning)
- 6.IPC (Instrument Panel Control Module)
- 7.PAM (Parking Aid Module)
- 8.PCM (Powertrain Control Module)
- 9.RCM (Restraint Control Module)
- 10.SRM (Speech Recognition Module)
- 11.TRM (Trailer Module)