Make	ТОУОТА		
Model	YARIS 1.5 Xi 5Dr		
Vin	MR2K29F350113019)	
Engine Specifications	1.5	Petrol	V
Vehicle Type	H/B		

Year	2018
Km	77778
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Good Condition	~
Cluster	Within Specification	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	V
Oil Filter	Within Specification	-	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Good Condition	V
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	-
Brake Fluid	Good Condition	-	Aircon Belt	No Cracks	-
Antifreeze	Good Condition		Multi V belt	No Cracks	_
Rear Main Seal	Not Applicable	-	Engine Mountings	Good Condition	-
Sump/Gasket	Not Applicable	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	lacksquare
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	~
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	-
Wheel Alignment	Within Specification	
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Not Applicable	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Within Specification	—
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	V
Clutch Cable	Not Applicable	V
Gearbox	Good Condition	V
Gear & Diff oil	Within Specification	V
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	V
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	▼

Concluding Remarks			

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	15-Oct-2024



