

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/11/2024 15:26:21

Technician Name:shaun

Vehicle Information

Make:NISSAN

VIN:adnusr1d5u0131247

Displacement:G 1.4 DOHC

Odometer:147390 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

1.Body Control System(BCM)