

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-07-22 07:57:02

Technician Name:Riaan

Customer Name:citton cars

Order no:

Service fee:

Notes:

Vehicle Information

Year:2014

Make:CHANGCHENG

Model:HAVAL H6

VIN:LGWEF4A57EF632169

Displacement:G 1.6 MPI

Odometer:131419 km

Vehicle Software Version:V10.30

Inspection Result

BCM (Body Control Module) 1 problems exist

1.C7,D0,11,29 Please Refer To The Relevant Manual.

N/A

The following systems are OK:

1.ECM (Engine Control Module)

2.ESP (Electrical Stable Program)(China V)

3.ABM (Airbag Module)(Auto-live CN5)

4.IP (Instrument Panel)(China V)