

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:10/30/2024 16:35:47

Technician Name:Raymond

Vehicle Information

Make:RENAULT

Model:KADJAR

VIN:VF1RFE00154832710

Odometer:120668 km

Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.IC (Instrument Cluster)
- 4.UCH
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.AC (Air Conditioning)
- 7.Parking Brake
- 8.UPC
- 9.Radio
- 10.Multimedia Interface