

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-09-06 12:01:00

Technician Name:shaun

Order no:

Service fee:

Notes:

Vehicle Information

Make:NISSAN

Odometer:211063 km

Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

1.ENGINE

2.METER/M&A

3.BCM

4.AIR BAG

5.HVAC

6.IPDM E/R

7.ALL MODE AWD/4WD