

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 2024-06-05 08:09:53

Technician Name: Eugene

Order no:

Service fee:

Notes:

Vehicle Information

Make: VW

VIN: WWZZZ16ZEM033757

Displacement: G 1.4 MPI

Odometer: 116270 km

Vehicle Software Version: V10.22

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.16 Steering Column Electronics Systems
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.25 Anti-Theft Immobilizer
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.56 Radio
- 14.69 Trailer Function
- 15.77 Telephone