Make	NISSAN	
Model	ALMERA 1.5 ACENTA	
Vin	MDHBBAN17Z073378	37
Engine Specifications	1.5	Petrol
Vehicle Type	S/D	

Year	2021
Km	92805
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>-</b>	Aircon Controls	Good Condition	<b>~</b>
Cluster	Within Specification	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	<b>~</b>	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	Good Condition	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	Good Condition	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition		Aircon Belt	Good Condition	•
Antifreeze	Good Condition		Multi V belt	Good Condition	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	Good Condition	-
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	Within Specification	<b>—</b>
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>—</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	-
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	<b>V</b>

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	<b>T</b>
Clutch Cable	Not Applicable	<b>T</b>
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	<b>T</b>
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	<b>~</b>

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	09-Oct-2024



