



Make	KIA	
Model	RIO 1.4 LX 5DR	
Vin	KNADC514LL6435268	
Engine Specifications	1.4	Petrol <input type="checkbox"/>
Vehicle Type	H/B	
Service Plan	N/A	

Year	2020	
Km	35268	
Transmission	Manual	<input type="checkbox"/>
Colour	GREY	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Working Condition	<input type="checkbox"/>	Aircon Controls	Working Condition	<input type="checkbox"/>
Cluster	Working Condition	<input type="checkbox"/>	Electric Windows	Working Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Not Applicable	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	77747 Km		Dip Stick	No Visible Leaks	<input type="checkbox"/>
Oil Filter	No Visible Leaks	<input type="checkbox"/>	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	Not Applicable	<input type="checkbox"/>	Fan Belt	Not Applicable	<input type="checkbox"/>
Air Filter	Good Condition	<input type="checkbox"/>	Fan belt Tensioner	Not Applicable	<input type="checkbox"/>
Cabin Filter	Good Condition	<input type="checkbox"/>	Alternator Belt	Not Applicable	<input type="checkbox"/>
Spark Plugs	Good Condition	<input type="checkbox"/>	Power Steering Belt	Not Applicable	<input type="checkbox"/>
Brake Fluid	Good Condition	<input type="checkbox"/>	Aircon Belt	Not Applicable	<input type="checkbox"/>
Antifreeze	No Visible Leaks	<input type="checkbox"/>	Multi V belt	No Cracks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Good Condition	<input type="checkbox"/>
Front Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Brake Pads	-Select-	<input type="checkbox"/>
Rear Brake Discs	Not Applicable	<input type="checkbox"/>
Rear Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Drums	Good Condition	<input type="checkbox"/>
Rear Linings	80%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	No Visible Leaks	<input type="checkbox"/>
Brake Hose	No Visible Leaks	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	No Visible Leaks	<input type="checkbox"/>
Aircon Pump	No Visible Leaks	<input type="checkbox"/>
Aircon Condensor	No Visible Leaks	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	No Visible Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	No Visible Leaks	<input type="checkbox"/>
Injectors	No Visible Leaks	<input type="checkbox"/>
Fuel Pump	No Visible Leaks	<input type="checkbox"/>
Fuel Lines	No Visible Leaks	<input type="checkbox"/>

Ignition System		
Ignition Coils	Good Condition	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distributor	Good Condition	<input type="checkbox"/>
HT Leads	Good Condition	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="button" value="v"/>
Power Steering Pump	Good Condition	<input type="button" value="v"/>
Wheel Alignment	Good Condition	<input type="button" value="v"/>
CV Joints	Good Condition	<input type="button" value="v"/>
CV Boots	Good Condition	<input type="button" value="v"/>
Shocks Front	Good Condition	<input type="button" value="v"/>
Shock Mountings Front	Good Condition	<input type="button" value="v"/>
Shocks Rear	Good Condition	<input type="button" value="v"/>
Stabilizer Links	Good Condition	<input type="button" value="v"/>
Wheel Bearings	Good Condition	<input type="button" value="v"/>
Bearing Hubs	Good Condition	<input type="button" value="v"/>
Control Arms	Good Condition	<input type="button" value="v"/>
Sideshafts/Seal	No Visible Leaks	<input type="button" value="v"/>
Propshaft	Not Applicable	<input type="button" value="v"/>
Wheel Nuts/Studs	Good Condition	<input type="button" value="v"/>
Tyres & Spare	Good Condition	<input type="button" value="v"/>
Mag Wheels/Hub Caps	Good Condition	<input type="button" value="v"/>

Transmission & Clutch		
Clutch Kit	Good Condition	<input type="button" value="v"/>
Clutch Master	Good Condition	<input type="button" value="v"/>
Clutch Slave	Good Condition	<input type="button" value="v"/>
Clutch Cable	Not Applicable	<input type="button" value="v"/>
Gearbox	Good Condition	<input type="button" value="v"/>
Gear & Diff oil	No Visible Leaks	<input type="button" value="v"/>
Auto Transmission	Not Applicable	<input type="button" value="v"/>
Gear Selector	Good Condition	<input type="button" value="v"/>
Gear Linkages	Good Condition	<input type="button" value="v"/>

Ignition System		
Diagnostics	Good Condition	<input type="button" value="v"/>
Cyl Leakage Test	No Visible Leaks	<input type="button" value="v"/>
Road Test	Good Condition	<input type="button" value="v"/>
Handling	Good Condition	<input type="button" value="v"/>

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

JOHN TSIPA

Date of Inspection

29-Jan-2025