



| | | |
|-----------------------|-------------------|---------------------------------|
| Make | SUZUKI | |
| Model | JIMNY 1.5 GLX | |
| Vin | JSAGJB74V00135590 | |
| Engine Specifications | 1.5 | Petrol <input type="checkbox"/> |
| Vehicle Type | | |
| Service Plan | N/A | |

| | | |
|---------------|-------------------|--------------------------|
| Year | 2020 | |
| Km | 91399 | |
| Transmission | Manual | <input type="checkbox"/> |
| Colour | BEIGE | |
| Branch | Bosch Car Service | |
| Warranty Plan | N/A | |

Interior

| | | | | | |
|-----------------------|----------------|--------------------------|------------------|----------------|--------------------------|
| Radio / Entertainment | Good Condition | <input type="checkbox"/> | Aircon Controls | Good Condition | <input type="checkbox"/> |
| Cluster | Good Condition | <input type="checkbox"/> | Electric Windows | Good Condition | <input type="checkbox"/> |

Exterior

| | | | | | |
|-------------------------|----------------|--------------------------|--------------|----------------|--------------------------|
| Windscreen | Good Condition | <input type="checkbox"/> | Mag Wheels | Good Condition | <input type="checkbox"/> |
| Side Mirrors / Electric | Good Condition | <input type="checkbox"/> | Wiper Blades | Not Applicable | <input type="checkbox"/> |

BOSCH VEHICLE INSPECTION

Engine

| | | | | | |
|--------------------|------------------|--------------------------|---------------------|------------------|--------------------------|
| Oil Service | 91403 Km | | Dip Stick | No Visible Leaks | <input type="checkbox"/> |
| Oil Filter | No Visible Leaks | <input type="checkbox"/> | Oil Filler Cap | No Visible Leaks | <input type="checkbox"/> |
| Fuel/Diesel Filter | No Visible Leaks | <input type="checkbox"/> | Fan Belt | Not Applicable | <input type="checkbox"/> |
| Air Filter | Good Condition | <input type="checkbox"/> | Fan belt Tensioner | Good Condition | <input type="checkbox"/> |
| Cabin Filter | Good Condition | <input type="checkbox"/> | Alternator Belt | Not Applicable | <input type="checkbox"/> |
| Spark Plugs | Good Condition | <input type="checkbox"/> | Power Steering Belt | Not Applicable | <input type="checkbox"/> |
| Brake Fluid | Good Condition | <input type="checkbox"/> | Aircon Belt | Not Applicable | <input type="checkbox"/> |
| Antifreeze | No Visible Leaks | <input type="checkbox"/> | Multi V belt | Not Applicable | <input type="checkbox"/> |
| Rear Main Seal | No Visible Leaks | <input type="checkbox"/> | Engine Mountings | Good Condition | <input type="checkbox"/> |
| Sump/Gasket | No Visible Leaks | <input type="checkbox"/> | PCV Valve | Good Condition | <input type="checkbox"/> |

| Braking System | | |
|--------------------|------------------|--------------------------|
| Front Brake Pads | 60% | <input type="checkbox"/> |
| Front Brake Discs | Good Condition | <input type="checkbox"/> |
| Front Brake Sensor | Good Condition | <input type="checkbox"/> |
| Rear Brake Pads | -Select- | <input type="checkbox"/> |
| Rear Brake Discs | Not Applicable | <input type="checkbox"/> |
| Rear Brake Sensor | Good Condition | <input type="checkbox"/> |
| Rear Drums | Good Condition | <input type="checkbox"/> |
| Rear Linings | 80% | <input type="checkbox"/> |
| Brake Master | Good Condition | <input type="checkbox"/> |
| Hand Brake | Good Condition | <input type="checkbox"/> |
| Brake Calipers | No Visible Leaks | <input type="checkbox"/> |
| Brake Hose | No Visible Leaks | <input type="checkbox"/> |

| Cooling System | | |
|-------------------|------------------|--------------------------|
| Radiator | No Visible Leaks | <input type="checkbox"/> |
| Radiator Hoses | No Visible Leaks | <input type="checkbox"/> |
| Waterpump | No Visible Leaks | <input type="checkbox"/> |
| Thermostat | No Visible Leaks | <input type="checkbox"/> |
| Aircon Gas | No Visible Leaks | <input type="checkbox"/> |
| Aircon Pump | No Visible Leaks | <input type="checkbox"/> |
| Aircon Condensor | No Visible Leaks | <input type="checkbox"/> |
| Interior Fan | Good Condition | <input type="checkbox"/> |
| Interior Radiator | No Visible Leaks | <input type="checkbox"/> |

| Fueling System | | |
|-----------------|------------------|--------------------------|
| Intake Manifold | No Visible Leaks | <input type="checkbox"/> |
| Throttle | No Visible Leaks | <input type="checkbox"/> |
| Turbo | Not Applicable | <input type="checkbox"/> |
| Injectors | No Visible Leaks | <input type="checkbox"/> |
| Fuel Pump | No Visible Leaks | <input type="checkbox"/> |
| Fuel Lines | No Visible Leaks | <input type="checkbox"/> |

| Ignition System | | |
|-----------------|----------------|--------------------------|
| Ignition Coils | Good Condition | <input type="checkbox"/> |
| Glow Plugs | Not Applicable | <input type="checkbox"/> |
| Distrubutor | Not Applicable | <input type="checkbox"/> |
| HT Leads | Good Condition | <input type="checkbox"/> |

| Steering & Suspension | | |
|-----------------------|------------------|----------------------------------|
| Steering Rack | Good Condition | <input type="button" value="v"/> |
| Power Steering Pump | Good Condition | <input type="button" value="v"/> |
| Wheel Alignment | Good Condition | <input type="button" value="v"/> |
| CV Joints | Good Condition | <input type="button" value="v"/> |
| CV Boots | Good Condition | <input type="button" value="v"/> |
| Shocks Front | Good Condition | <input type="button" value="v"/> |
| Shock Mountings Front | Good Condition | <input type="button" value="v"/> |
| Shocks Rear | Good Condition | <input type="button" value="v"/> |
| Stabilizer Links | Good Condition | <input type="button" value="v"/> |
| Wheel Bearings | Good Condition | <input type="button" value="v"/> |
| Bearing Hubs | Good Condition | <input type="button" value="v"/> |
| Control Arms | Good Condition | <input type="button" value="v"/> |
| Sideshafts/Seal | No Visible Leaks | <input type="button" value="v"/> |
| Propshaft | Good Condition | <input type="button" value="v"/> |
| Wheel Nuts/Studs | Good Condition | <input type="button" value="v"/> |
| Tyres & Spare | Not Applicable | <input type="button" value="v"/> |
| Mag Wheels/Hub Caps | Good Condition | <input type="button" value="v"/> |

| Transmission & Clutch | | |
|-----------------------|------------------|----------------------------------|
| Clutch Kit | Good Condition | <input type="button" value="v"/> |
| Clutch Master | Good Condition | <input type="button" value="v"/> |
| Clutch Slave | Good Condition | <input type="button" value="v"/> |
| Clutch Cable | Good Condition | <input type="button" value="v"/> |
| Gearbox | No Visible Leaks | <input type="button" value="v"/> |
| Gear & Diff oil | No Visible Leaks | <input type="button" value="v"/> |
| Auto Transmission | Not Applicable | <input type="button" value="v"/> |
| Gear Selector | Good Condition | <input type="button" value="v"/> |
| Gear Linkages | Good Condition | <input type="button" value="v"/> |

| Ignition System | | |
|------------------|------------------|----------------------------------|
| Diagnostics | Good Condition | <input type="button" value="v"/> |
| Cyl Leakage Test | No Visible Leaks | <input type="button" value="v"/> |
| Road Test | Good Condition | <input type="button" value="v"/> |
| Handling | Good Condition | <input type="button" value="v"/> |

| Concluding Remarks | |
|--------------------|--|
| | |

| Bosch Technician | |
|---|--|
| -Select- <input type="button" value="v"/> | |

| General Comments | |
|------------------|--|
| | |

| NEW Technician | |
|----------------|--|
| JOHN TSIPA | |

| Date of Inspection | |
|--------------------|--|
| | |