

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-09-26 11:47:00

Technician Name:john

Order no:

Service fee:

Notes:

## Vehicle Information

Make:SUZUKI

VIN:JSAGJB74V00135590

Displacement:G 1.4 MPI KAPPA

Odometer:91403 miles

Vehicle Software Version:V10.36

## Inspection Result

The following systems are OK:

- 1.ECM ( Engine Control Module )
- 2.ABS ( Anti-Lock Braking System )
- 3.EPS ( Electronic Power Steering )
- 4.SRS ( Supplemental Inflatable Restraint System/Airbag )
- 5.BCM ( Body Control Module )
- 6.IPC ( Combination Meter / Meter/ M&A )
- 7.ALC ( Headlight Auto Leveling )
- 8.CSW ( Lighting And Turn Signal )
- 9.CGW ( Central Gateway Control Module )
- 10.4WD ( 4 Wheel Drive )