Make	ТОУОТА		
Model	AYGO 1.0 (5DR)		
Vin	JTDKG0ECX0N1358	34	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2016
Km	97440
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	lacksquare

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	_
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code  ▼		Power Steering Belt	Not Applicable	_
Brake Fluid	No Visible Leaks  ▼		Aircon Belt	No Cracks	-
Antifreeze	No Visible Leaks  ▼		Multi V belt	No Cracks	-
Rear Main Seal	No Visible Leaks  ▼		Engine Mountings	Within Specification	_
Sump/Gasket	No Visible Leaks  ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	lacksquare
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	lacksquare
Rear Drums	Within Specification	lacksquare
Rear Linings	60%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	<b>V</b>
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	
Shocks Front	No Visible Leaks	
Shock Mountings Front	Within Specification	
Shocks Rear	No Visible Leaks	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	

Transmission & Clutch		
Clutch Kit	Good Condition	<b>—</b>
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	lacksquare
Clutch Cable	Within Specification	<b>—</b>
Gearbox	No Visible Leaks	<b>—</b>
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



