Make	MERCEDES-BENZ
Model	C200 COUPE A/T
Vin	WDD2053802F835970
Engine Specifications	Petrol
Vehicle Type	C/P

Year	2020
Km	61429
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	~	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	V
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	V
Oil Filter	No Visible Leaks ▼		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	V
Spark Plugs	No Fault Code ▼		Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	~
Antifreeze	Within Specification		Multi V belt	No Cracks	~
Rear Main Seal	No Visible Leaks ▼		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	No Fault Code	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	No Fault Code	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	No Fault Code	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	~
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	No Fault Code	
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	~
Wheel Nuts/Studs	Within Specification	~
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	—
Clutch Master	Not Applicable	\
Clutch Slave	Not Applicable	\
Clutch Cable	Not Applicable	T
Gearbox	No Visible Leaks	T
Gear & Diff oil	Within Specification	—
Auto Transmission	Within Specification	—
Gear Selector	Within Specification	—
Gear Linkages	Within Specification	v

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	~
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding hemarks	
Bosch Technician	General Comments
Boscii Techinician	General Comments
Dries Olwagen ▼	
NEW Technician	Date of Inspection



