

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Sn:988579800333

Time:2024-10-18 07:05:04

Technician Name:Eugene

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2011.12

Make:MINI

Model:One

VIN:WMWSR32080T336276

Odometer:130945 km

Vehicle Software Version:V10.30

## Inspection Result

The following systems are OK:

- 1.CAS (Car Access System - CAS/FEM/BDC)
- 2.ECM (Engine Control Module - DME/DDE)
- 3.ABS (Anti-Lock Braking System - DSC)
- 4.EPS (Electronic Power Steering)
- 5.SGM-ZGM (Safety And Gateway Module (ZGM) - JBE/JBE2/JBBF/KGM)
- 6.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 7.SZL (Switch Center, Steering Column)
- 8.IC (Instrument Cluster - INSTR)
- 9.CD (Control Display - CIC/CCC-BO/CHAMP-BO/M-ASK-BO/RAD/RAD2-BO)
- 10.FRM (Footwell Module)
- 11.AC (Air Conditioning - IHKA)