Make	ALFA ROMEO		
Model	GIULIA 2.0T VELOCE		
Vin	ZAREAEJN0H753632	2	
Fraire Cresifications			
Engine Specifications	2.0	Petrol	
Vehicle Type	S/D	Petrol	

Year	2022
Km	102650
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	<b>~</b>	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION				
Engine				
Oil Service		Km	Dip Stick	Good Condition
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition
Antifreeze	Good Condition	•	Multi V belt	Good Condition
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition

Braking System		
Front Brake Pads	60%	<b>—</b>
Front Brake Discs	Good Condition	•
Front Brake Sensor	Good Condition	<b>—</b>
Rear Brake Pads	60%	<b>—</b>
Rear Brake Discs	Good Condition	<b>—</b>
Rear Brake Sensor	Good Condition	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	<b>—</b>
Brake Calipers	Good Condition	<b>—</b>
Brake Hose	Good Condition	<b>—</b>

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	<b>—</b>
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	<b>V</b>

Fueling System		
Intake Manifold	Good Condition	-
Throttle	Good Condition	lacksquare
Turbo	Good Condition	lacksquare
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	lacksquare

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Good Condition	lacksquare



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	<b>—</b>
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	<b>V</b>
CV Joints	Good Condition	<b>V</b>
CV Boots	Good Condition	<b>V</b>
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	<b>V</b>
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	lacksquare
Sideshafts/Seal	Good Condition	<b>V</b>
Propshaft	Good Condition	<b>V</b>
Wheel Nuts/Studs	Good Condition	<b>v</b>
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	<b>T</b>

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	<b>~</b>

Bosch Technician	General Comments
Basal Johnson	
NEW Technician	Date of Inspection
	15-Aug-2024



**Concluding Remarks** 

