

# Bosch Service Inspection Certificate



BATTERY DETAILS

Inspection No:

± Age 2023  
 Make Ford Everest No. 2.017

Registration No: LL07ZT9P

Job Card No: 3533467

SERVICE	OK	Not Ok	Rectified	BREAKING SYSTEM	OK	Not Ok	Rectified	STEERING SYSTEM	OK	Not Ok	Rectified		
1 Service	✓			50 Brake Fluid	✓			100 Ball Joints	✓				
2 Spark Plugs	✓			51 Disc Pads Front	✓			101 Tie Rod Ends	✓				
3 Points & Condenser	✓			52 Pad Sensors Front	✓			102 Control Arm	✓				
4 Oil	✓			53 Discs Front	✓			103 Drag Link	✓				
5 Oil Filter	✓			54 Brake Calliper	✓			104 Stabiliser Arm	✓				
6 Fuel Filter	✓			55 Brake Calliper Leak(s)	✓			<b>DRIVE LINE</b>			OK	Not Ok	Rectified
7 Air Filter	✓			56 Disc Pads Rear	✓			105 Side Shaft Oil Leak(s)	✓				
8 Pollen Filter	✓			57 Pad Sensors Rear	✓			106 Front Wheel Bearings	✓				
9 Other Filter(s)	✓			58 Drums Rear	✓			107 Front Bearing Hubs	✓				
10 Wiper Blades	✓			59 Disc Rear	✓			108 Rear Wheel Bearings	✓				
11 Windscreen Washers	✓			60 Rear Linings	✓			109 Rear Wheel Bearing Hubs	✓				
12 Pedal Rubbers	✓			61 Rear Cylinders	✓			110 CV Shafts	✓				
<b>ADDITIVES MISC</b>				62 Rear Cylinder Leak(s)	✓			111 CV Boots	✓				
13 Brake Cleaner	✓			63 Handbrake Lining	✓			112 Shocks	✓				
14 Radiator Flush	✓			64 Handbrake Cable	✓			113 Springs	✓				
15 Carb Cleaner	✓			65 Brake Master Cylinder	✓			114 Shock Mountings	✓				
16 Engine Flush	✓			66 Master Cylinder Leak(s)	✓			115 Wheel Nuts/Studs	✓				
<b>TRANSMISSION</b>				67 ABS System	✓			116 Tyres & Spare Pressure	✓				
17 Transmission	✓			68 Brake Hoses	✓			117 Tyres & Spare Condition	✓				
18 Transmission Oil	✓			<b>CLUTCH SYSTEM</b>			OK	Not Ok	Rectified	118 Grease Points	✓		
19 Transmission Oil Leak(s)	✓			69 Clutch Fluid	✓			119 Prop Shaft(s)	✓				
20 Transfer Box	✓			70 Clutch Operation	✓			<b>EXHAUST SYSTEM</b>			OK	Not Ok	Rectified
21 Transfer Box Oil	✓			71 Clutch Master	✓			120 Exhaust Silencer	✓				
22 Transfer Box air Leak(s)	✓			72 Clutch Master Leak	✓			121 Catalytic Converter	✓				
23 Differential	✓			73 Clutch Slave	✓			122 Flange Gasket	✓				
24 Differential Oil	✓			74 Clutch Slave Leak	✓			123 Exhaust Manifold Gasket	✓				
25 Differential Oil Leak(s)	✓			75 Clutch Cable	✓			124 Turbo Gasket(s)	✓				
26 Differential Lock	✓			<b>COOLING SYSTEM</b>			OK	Not Ok	Rectified	125 Hangers	✓		
27 Differential Mounting(s)	✓			76 Water Leaks	✓			<b>ELECTRICAL</b>			OK	Not Ok	Rectified
28 Transmission Mounting	✓			77 Reservoir Bottle	✓			126 ECU	✓				
<b>ENGEN</b>				78 Antifreeze	✓			127 Headlights - Dim	✓				
29 Engine Oil Leak(s)	✓			79 Cooling Fan	✓			128 Headlights - Bright	✓				
30 Oil Filler Cap	✓			80 Radiator Hoses	✓			129 Fog Lights	✓				
31 Cam Belt	✓			81 Water Pump	✓			130 Brake Lights	✓				
32 Cam Belt Tensioner	✓			82 Thermostat	✓			131 Park Lights	✓				
33 Drive Belt(s)/V-Belt(s)	✓			83 Radiator	✓			132 Dash Lights	✓				
34 Tensioner/Pulleys	✓			84 Cooling System Pressure Test	✓			133 Interior Lights	✓				
35 Hydraulic Lifters	✓			85 Hose Clamps	✓			134 Flicker Lights Left	✓				
36 Tappet Noise	✓			86 Radiator Cap	✓			135 Flicker Lights Right	✓				
37 Throttle Assembly	✓			87 Cap Pressure Test	✓			136 Spot Lights	✓				
38 Turbo	✓			<b>IGNITION SYSTEM</b>			OK	Not Ok	Rectified	137 Reverse Light(s)	✓		
39 Carburetor	✓			88 Coil(s)	✓			138 Starter	✓				
40 Injectors	✓			89 Distributor	✓			139 Alternator	✓				
41 Fuel Pump	✓			90 Distributor Cap	✓			140 Battery	✓				
42 Fuel Line	✓			91 Rotor	✓			141 Battery Terminals	✓				
43 Vacuum System	✓			92 High Tension Leads	✓			142 Battery Water	✓				
44 Relative Compression Test	✓			<b>STEERING SYSTEM</b>			OK	Not Ok	Rectified	143 Power Windows	✓		
45 Engine Mounting	✓			93 Steering System	✓			144 Side Mirrors	✓				
<b>AIR CONDITIONER</b>				94 Steering System Leak(s)	✓			145 Instrument	✓				
46 Climate Control	✓			95 Power Steering Pump	✓			146 Sensors	✓				
47 Climate Temp	✓			96 Power Steering Fluid	✓			147 Seat Belts	✓				
48 Compressor	✓			97 Power Steering Pipes	✓			148 Seats	✓				
49 Service Air-Con System	✓			98 Steering Boots	✓			149 Diagnostic Check	✓				
				99 Steering Rack	✓			150 Hooter	✓				

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

ROAD TEST

Performance ✓  
 Noise ✓  
 Handling ✓  
 Transmission ✓  
 Clutch ✓

Brakes ✓  
 Vibrations ✓  
 Wheel Alignment ✓  
 Wheel Balancing ✓

BCS DEALERSHIP DECLARATION

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and of sound mechanical condition.

Date: 06/01/2025

Technician Name: Ricardo

Signature:

Service Advisor/Managers Name: \_\_\_\_\_  
 print name

Signature: \_\_\_\_\_