

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16140

Make	ISUZU
Model	D-MAX 250C FLEETSIDE S/C P/U
Vin	ACVMRRAR9J4037370
Engine Specifications	Diesel
Vehicle Type	S/C
Service Plan	N/A

Year	2019
Km	159607
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Working Condition	•
Cluster	Within Specification	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Not Applicable	•	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Oil Service		159607 Km	Dip Stick	Within Specification
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification
Spark Plugs	Within Specification	•	Power Steering Belt	Within Specification
Brake Fluid	Within Specification	•	Aircon Belt	Within Specification
Antifreeze	Within Specification	•	Multi V belt	Within Specification
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	<b>~</b>
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	• •
CV Boots	Not Applicable	
Shocks Front	Within Specification	-
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	-
Sideshafts/Seal	Within Specification	-
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	-

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	<b>~</b>
Road Test	Within Specification	-
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

-Select-

## General Comments

NEW Technician

CHRISTIAAN

#### Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

