

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:12/17/2024 10:51:23
Technician Name:John

Vehicle Information

Make:JPISUZU
VIN:ACVNRHR6J4037515
Odometer:75931 km
Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-Lock Braking System)
- 3.EBS (Electronic Brake System)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.IMMO (Immobiliser)