

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 17265

Make	MAZDA	
Model	BT-50 3.2TDi SLE 4X4	4 A/T P/U D/C
Vin	MM6UR0YF1H073789	91
Engine Specifications	3.2	Diesel
Vehicle Type	D/C	
Service Plan	N/A	

Year	2017
Km	124744
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	-	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification
Oil Filter	Good Condition	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	No Visible Leaks	Fan Belt	Not Applicable
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	No Cracks
Spark Plugs	Not Applicable	Power Steering Belt	No Cracks
Brake Fluid	Within Specification	Aircon Belt	No Cracks
Antifreeze	Within Specification	Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	-
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	-
Turbo	No Fault Code	-
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	-
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	No Visible Leaks	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Dries Olwagen

NEW Technician

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

