



| | | |
|-----------------------|-----------------------|---------------------------------|
| Make | HYUNDAI | |
| Model | GRAND i10 1.25 MOTION | |
| Vin | MALA851CLJM738168 | |
| Engine Specifications | 1.2 | Petrol <input type="checkbox"/> |
| Vehicle Type | H/B | |
| Service Plan | N/A | |

| | | |
|---------------|-------------------|--------------------------|
| Year | 2018 | |
| Km | 94082 | |
| Transmission | Manual | <input type="checkbox"/> |
| Colour | WHITE | |
| Branch | Bosch Car Service | |
| Warranty Plan | N/A | |

Interior

| | | | | | |
|-----------------------|----------------|--------------------------|------------------|----------------|--------------------------|
| Radio / Entertainment | Good Condition | <input type="checkbox"/> | Aircon Controls | Good Condition | <input type="checkbox"/> |
| Cluster | Good Condition | <input type="checkbox"/> | Electric Windows | Not Applicable | <input type="checkbox"/> |

Exterior

| | | | | | |
|-------------------------|----------------|--------------------------|--------------|----------------|--------------------------|
| Windscreen | Good Condition | <input type="checkbox"/> | Mag Wheels | Good Condition | <input type="checkbox"/> |
| Side Mirrors / Electric | Good Condition | <input type="checkbox"/> | Wiper Blades | Not Applicable | <input type="checkbox"/> |

BOSCH VEHICLE INSPECTION

Engine

| | | | | | |
|--------------------|----------------------|--------------------------|---------------------|----------------------|--------------------------|
| Oil Service | SERVICE DUE Km | | Dip Stick | Within Specification | <input type="checkbox"/> |
| Oil Filter | Not Applicable | <input type="checkbox"/> | Oil Filler Cap | No Visible Leaks | <input type="checkbox"/> |
| Fuel/Diesel Filter | Within Specification | <input type="checkbox"/> | Fan Belt | No Cracks | <input type="checkbox"/> |
| Air Filter | Within Specification | <input type="checkbox"/> | Fan belt Tensioner | Within Specification | <input type="checkbox"/> |
| Cabin Filter | Within Specification | <input type="checkbox"/> | Alternator Belt | No Cracks | <input type="checkbox"/> |
| Spark Plugs | Within Specification | <input type="checkbox"/> | Power Steering Belt | Not Applicable | <input type="checkbox"/> |
| Brake Fluid | Good Condition | <input type="checkbox"/> | Aircon Belt | No Cracks | <input type="checkbox"/> |
| Antifreeze | Good Condition | <input type="checkbox"/> | Multi V belt | No Cracks | <input type="checkbox"/> |
| Rear Main Seal | Not Applicable | <input type="checkbox"/> | Engine Mountings | Good Condition | <input type="checkbox"/> |
| Sump/Gasket | Not Applicable | <input type="checkbox"/> | PCV Valve | Within Specification | <input type="checkbox"/> |

| Braking System | | |
|--------------------|----------------------|--------------------------|
| Front Brake Pads | 60% | <input type="checkbox"/> |
| Front Brake Discs | Within Specification | <input type="checkbox"/> |
| Front Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Brake Pads | -Select- | <input type="checkbox"/> |
| Rear Brake Discs | Not Applicable | <input type="checkbox"/> |
| Rear Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Drums | Within Specification | <input type="checkbox"/> |
| Rear Linings | 80% | <input type="checkbox"/> |
| Brake Master | Good Condition | <input type="checkbox"/> |
| Hand Brake | Within Specification | <input type="checkbox"/> |
| Brake Calipers | Good Condition | <input type="checkbox"/> |
| Brake Hose | No Visible Leaks | <input type="checkbox"/> |

| Cooling System | | |
|-------------------|----------------------|--------------------------|
| Radiator | Within Specification | <input type="checkbox"/> |
| Radiator Hoses | No Visible Leaks | <input type="checkbox"/> |
| Waterpump | Within Specification | <input type="checkbox"/> |
| Thermostat | Within Specification | <input type="checkbox"/> |
| Aircon Gas | Good Condition | <input type="checkbox"/> |
| Aircon Pump | Within Specification | <input type="checkbox"/> |
| Aircon Condensor | Good Condition | <input type="checkbox"/> |
| Interior Fan | Good Condition | <input type="checkbox"/> |
| Interior Radiator | No Visible Leaks | <input type="checkbox"/> |

| Fueling System | | |
|-----------------|----------------------|--------------------------|
| Intake Manifold | Within Specification | <input type="checkbox"/> |
| Throttle | Within Specification | <input type="checkbox"/> |
| Turbo | Not Applicable | <input type="checkbox"/> |
| Injectors | Within Specification | <input type="checkbox"/> |
| Fuel Pump | Within Specification | <input type="checkbox"/> |
| Fuel Lines | No Visible Leaks | <input type="checkbox"/> |

| Ignition System | | |
|-----------------|----------------------|--------------------------|
| Ignition Coils | Within Specification | <input type="checkbox"/> |
| Glow Plugs | Not Applicable | <input type="checkbox"/> |
| Distrubutor | Not Applicable | <input type="checkbox"/> |
| HT Leads | Within Specification | <input type="checkbox"/> |

| Steering & Suspension | | |
|-----------------------|----------------------|--------------------------|
| Steering Rack | Within Specification | <input type="checkbox"/> |
| Power Steering Pump | Not Applicable | <input type="checkbox"/> |
| Wheel Alignment | Within Specification | <input type="checkbox"/> |
| CV Joints | Good Condition | <input type="checkbox"/> |
| CV Boots | Good Condition | <input type="checkbox"/> |
| Shocks Front | Good Condition | <input type="checkbox"/> |
| Shock Mountings Front | Good Condition | <input type="checkbox"/> |
| Shocks Rear | Good Condition | <input type="checkbox"/> |
| Stabilizer Links | Good Condition | <input type="checkbox"/> |
| Wheel Bearings | Good Condition | <input type="checkbox"/> |
| Bearing Hubs | Within Specification | <input type="checkbox"/> |
| Control Arms | Good Condition | <input type="checkbox"/> |
| Sideshafts/Seal | Not Applicable | <input type="checkbox"/> |
| Propshaft | Not Applicable | <input type="checkbox"/> |
| Wheel Nuts/Studs | Good Condition | <input type="checkbox"/> |
| Tyres & Spare | Good Condition | <input type="checkbox"/> |
| Mag Wheels/Hub Caps | Good Condition | <input type="checkbox"/> |

| Transmission & Clutch | | |
|-----------------------|----------------------|--------------------------|
| Clutch Kit | Not Applicable | <input type="checkbox"/> |
| Clutch Master | Within Specification | <input type="checkbox"/> |
| Clutch Slave | Not Applicable | <input type="checkbox"/> |
| Clutch Cable | Within Specification | <input type="checkbox"/> |
| Gearbox | Within Specification | <input type="checkbox"/> |
| Gear & Diff oil | Within Specification | <input type="checkbox"/> |
| Auto Transmission | Not Applicable | <input type="checkbox"/> |
| Gear Selector | Within Specification | <input type="checkbox"/> |
| Gear Linkages | Within Specification | <input type="checkbox"/> |

| Ignition System | | |
|------------------|------------------|--------------------------|
| Diagnostics | No Visible Leaks | <input type="checkbox"/> |
| Cyl Leakage Test | No Visible Leaks | <input type="checkbox"/> |
| Road Test | Good Condition | <input type="checkbox"/> |
| Handling | Good Condition | <input type="checkbox"/> |

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

RIAAN MEINTJIES

Date of Inspection

06-Aug-2024